





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb  
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD ..

Position


- 1 = A 960 645 XX
- 3 = B 960 473 XX
- 5 = A 960 646 XX
- 9 = A 962 985 NU
- 20 = A 960 649 NU
- 24 = A 962 470 NU
- 25 = A 960 653 XX
- 28 = A 960 654 XX
- 32 = A 961 230 XX
- 33 = A 960 196 NU




## ATTITUDE

A 4591 .. A 4594 .. A 4595 ..


0811 / A 866 004  
 (+ A 865 612)  
 Made in Germany




A 4595



A 4591















A 4594



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





	<b>P</b> bar	0,5	MAX. 10	5		<b>Q</b> (3 bar)
	<b>T</b> °C		MAX. 80	65		<b>13</b>
				40		<b>13</b>